

Htek IP phones Release Notes of Version

Introduction:

❖ Product Model:

UC926/UC926E/UC924/UC924E/UC912E/UC923/UC902/UC903/UC912/UC912G/UC901/UC862/UC842/UC860P/840P/806P/UC806G/UC806T/UC804P/UC804G/UC804T/803P/802P/UC802T

❖ Firmware Version:

UC8XX/UC9XX--2.0.4.6.15

❖ Release Date:

2019.01.23

Version: 2.0.4.6.15

New Add Features

- Added a hint for the firmware that the phone needs to be upgraded.

Delete Features

- N/A

Improve Features

- N/A

Fix issue

- Fixed an issue that gets phonebook by https.
- Fixed an issue with drawing DSS Key.
- Fixed an issue of E series accessing Web GUI access through https.
- Fixed an issue of time synchronization will wake up the phone from screen saver.

Version: 2.0.4.6.13

New Add Features

- N/A

Delete Features

- N/A

Improve Features

- N/A

Fix issue

- Fixed an issue when saving forward settings on the phone, the Arrow Navigation Key doesn't work for 2 second.
- Fixed an issue the phone would be stuck for a few seconds if dialing immediately after the last call ended.
- Fixed a connection issue with phone and Bluetooth.
- Fixed an issue that the phone cannot register after restarting the server.
- Fixed the daylight-saving time abnormality issue when switching back and forth between daylight saving time.
- Fixed a disk read and write issue that caused the GUI to get stuck.

Version: 2.0.4.6.12

New Add Features

- Remote phonebook supports TFTP and FTP transfer protocol, and the size of phonebook file is up to 512K.

Delete Features

- N/A

Improve Features

- Optimized SRTP call function.
- Optimized BroadSoft features synchronization.
 - ACD login & logout process.
 - Execute call pickup function by BLF List.
 - Keep the phone and BroadSoft platform Forward status in sync.
 - DSSKey will be cleared immediately when Flexible Seating Guest Out.
 - Blank BLFList DSSKey will be cleared when BLF List mode set as Automatically.
- Change ACD [Login/Logout] button to [Sign In/Sign Out].
- Modify the name and note of [SIP Date Override Time] & [Account (SIP Date Override Time)].

Fix issue

- Fixed a call park process issue.
- Fixed some crash issues
 - Hold & Resume when using ZRTP.
 - Try to get configuration file through the non-existent path in the Providecode file
- Fixed a Dial Plan issue.
- Fixed an issue where the volume heard by the receiver was too low.
- Fixed the UC926E Bluetooth pairing list is not accurate issue.

- Fixed the on-hook dial number loss issue after the phone connecting to Bluetooth.
- Fixed the Bluetooth auto connect failed issue when the UC926E Bluetooth link is in sleep mode.
- Fixed a transfer failed via *code issue.
- Fixed a transfer failed issue cause by input letters.
- Fixed an issue where the port of the Application layer and the IP layer sometimes did not match when using the TCP/TLS transport protocol.
- Fixed the Daylight-Saving Time work failure issue of E series phone.
- Fixed an issue where the phone did not send registration packets due to the BLF delay timer.
- Fixed an issue that adjust volume when Alert ring is ringing, the ringtone will be abnormal.

Hitek