

Htek IP phones Release Notes of Version

Introduction:

❖ Product Model:

UC926/UC926E/UC924/UC924E/UC912E/UC923/UC902/UC903/UC912/UC912G/UC901/UC921/UC921G/UC902S/UC862/UC842/UC860P/840P/806P/UC806G/UC806T/UC804P/UC804G/UC804T/803P/802P/UC802T/UC501/UC503/UC503G/UC505/UC507

❖ Firmware Version:

2.0.4.8.11

❖ Release Date:

2020.09.10

Version: 2.0.4.8.11

New Add Features

- The BT function removes the behavior of blocking the MAC address of the B_link manufacturer
- CDP, LLDP, and DHCP VLAN new mechanisms are incorporated

Delete Features

- N/A

Improve Features

- Jitter Buffer overflow prevention related changes Check and integration
- Copyright © 2005-2019 All Rights Reserved needs to be updated 2005-2020

Fix issue

- There is a problem with the DNS resolution of the LDAP server address of the phone, which causes the LDAP acquisition failure
- Caller ID Source not working
- The number of account options added to the directory page of the phone web page is inconsistent with the number of accounts on the actual phone
- Low volume when using the UC921 speaker
- Headset turns off on incoming call
- BLF Pick up fails
- IP Phone 902S LCD has no line key option
- There is no DTMF tone when the MTK phone is in the Idle state.
- The interface for modifying the password to send a long string RTL crashes
- Use the handset to call and press cancel, and then make a new call, the call is low or no voice
- Set the phonelock to Lock&Answer on the LCD, and the corresponding webpage displays disable
- UC912E turns on Bluetooth scan title bar without prompt
- When in the Idle state and no value is configured for Always Forward, pressing HardKey-Transfer has no response
- The line key disappears when UC902 is off-hook
- After saving the Voice page, it will jump to the SIP page
- Transfer type ignored if P20982 is set to 1
- When the length of Linekey is not default, the length of the edit area of the call window is abnormal
- BLF list cannot be used
- 2abc instead of abc in LDAP filter

- DHCP Seconds Elapsed is always 0, which results in the inability to restrict requests to addresses through the switch

Version: 2.0.4.8.5

New Add Features

- UC923M brightness adjustment LCD / WEB interface entrance(adds the function of adjusting and turning off the backlight).

Delete Features

- N/A

Improve Features

- N/A

Fix issue

- N/A

Version: 2.0.4.8.4

New Add Features

- The DUT uses the handset to talk. Press the DUT hold and then hang up the handset. The call is directly disconnected and does not switch to the Speaker state.

Delete Features

- N/A

Improve Features

- N/A

Fix issue

- Fixed the account password containing % 2 and % b, which is inconsistent with the original password after the phone is assigned.
- Fixed the restart of the phone page on the network page, the redirected page will have Undefined option.
- Fixed the prefix / Fuzzy search mode, the first letter of the name is uppercase, input uppercase or uppercase letters, can not find contacts.
- Fixed the 5XX model phone G722 makes noise immediately after answering.
- Fixed the length of ActionURL and & character.
- Fixed configuration failure via RPS assignment.
- Fixed the phone not responding when pressing the ok key of Auto Redial.

Version: 2.0.4.8.3

New Add Features

- IP Phone support TR069.

Delete Features

- N/A

Improve Features

- Filter and keyboard in remote directories.

Fix issue

- Fixed Phone does not revert to primary SIP server.