

Htek Company Introduction

Swww.htek.com



01 Who is Htek


02 Htek Products

03 Success Cases

- History
- A World Map of Htek


- UC9xx, UCV, UCV Pro IP Phones
- HPT, HDMS
- Technology Partners
- Customized Solutions

- Operators
- Htek & Mitel Success Cases









Htek Products

Audio IP Phones, Video IP Phones, Hotel IP Phones ...

UC900 Series IP Phones





Series Smart Video IP Phones




UCV Pro Seris Cordless Smart Video IP Phones



Customized Products





Multiple Functions :

Supports multiple functions including buttons, display, headset, hands-free, Bluetooth, Wi-Fi, etc.

Customized development:

We can provide unique function development and customization according to the specific needs of customers

Actual product application areas:

China, the United States, the United Kingdom, France, Spain, Australia, etc.

Device Management (Provisioning Tool - HPT)



HTTP Server: Stop PNP Server: Stop DM	Server: Stop Cfg	file: Load a Template Save	Save as uc926U_2.0.4.2_	_en 👻
Phone Configuration Cfg Batch Devices Discover Devices Manage Servers	Settings Tool			
	Account_1 Prim Account_2 Prim Account_3 Failo Account_4 Failo Account_5 Secc Account_6 Prefe Network_Basic DHC Network_PC_Port DHC Network_Advanced Outb © LineKey Back ® ProgrammableKey Back © EXP_KEY SIP Preference Failo Features NAT BLFSettings Labe Tones SIP SMS ActionURL ActionURL Auth SIP RemotePhonebook	CP SIP Server bound Proxy kup Outbound Proxy Transport Traversal el User ID nenticate ID nenticate Password blay Name	Yes ▼ 192.168.0.123 Image: Second	^
	wullcastraying	r ID Is Phone Number	No Ves	*

Htek Provision Tool - HPT tool

- Configuration files visual editing
- Configuration files batch generating
- All devices within the enterprise network
 overall management
- HTTP and PnP server integration

Device Management System: HDMS



• Graphical statistical analysis of equipment status

	41 1	ndex Timer Task O						N Close
Profile Management	Tan	ik Name:	Tas	k Content:	Repeat:		Status :	
Account Management		sk Name			~		*	~
	Cre	vater:	~					
Device Management (
Config Management	QS	aurch SReset						
Task Management ~	+^	80						
Timer Task		Task Name	Task Content	Repeat	Execution Time	Status	Creater	Operate
Executed Task	0	and sheet	Reboot	One-Time Task	2024-06-22 15:58:48 - 2024-0	End	Hte	0
Dashboard <			Push Config File	Daily	07:41:33 = 07:41:54	End	RR and R	0
Device Diagnosis		100.000	Reboot	One-Time Task	2023-08-07 13:55:08 - 2023-0	End	Sys	0
Alarm Management <		PLAN OF	Reboot	Daily	11:28:00 - 11:28:15	End	pat	0
System Management <		unar -	Reboot	Daily	11:12:00 - 11:12:30	End	patient, "statisting all	0
		-B-Milling-Indoct	Reboot	Dailty	07:00:00 ~ 07:05:00	Suspending	india _{pol} a il a	
		544	Rebuot	One-Time Task	2023-02-08 09:33:55 ~ 2023-0	Executing	Steallin //	11 0 0
		76,81	Reboot	One-Time Task	2023-02-06 09:30:18 ~ 2023-0	Executing	Ste	11 0 0
		+3	Reboot	One-Time Task	2023-02-08 09:21:31 - 2023-0	End	Step	0
	0	Sec.	Reboot	One-Time Task	2023-02-07 18:35:48 - 2023-0	End	Stell	0

• Scheduled task setting and execution management plan

	44	index Alarm List @								PF 1	Close
Profile Management		vice Name:		MAC:		IP :		Severity:			
-		vice Name		MAC		IP		uning :			¥
Account Management <	Ali	arm Type :									
Device Management			÷								
Config Management	QS	earch SRoset									
Task Management	80	ciote FEigurt									
Dashboard 4		Device Name	MAC	IP	Severity	Alarm Type	Alarm Date	Accu	imulated number of a	Operate	
Device Diagnosis (0	10	glader (research	0.0.0.0	Minor	Firmware upgrade failed	2024-07-11	1		121 0)
and a second second second	D	2	0e	192.168.66.218	Minor	Registration failed	2024-07-11	5		(Å) ()	,
Jarm Management 🤇	0	1/8/19/1	1.07	0.0.0.0	Minor	Registration failed	2024-07-11	1		0	,
stem Management, <	•	400.013.000 PL	inarra.so	192.168.3.14	Minor	Registration failed	2024-07-11	1		(Ĉ) (,
		Charms of		10.3.8.131	Minor	Registration failed	2024-07-11	2		0	,
	0	5850-	100010-001	192.168.66.217	Minor	Registration failed	2024-07-11	6		1 Ö 1 Ö)
	0	Arriant watchedd	-	192.168.0.174	Minor	Registration failed	2024-07-11	4		0 (1)	,
	0	diddy glanger	#47.940e	182.168.100.133	Minor	Registration failed	2024-07-11	329		0 131	,
		Ang	nin ing populat	192.168.30.132	Minor	Firmware upgrade failed	2024-07-11	1		1 <u>0</u>)
i i	0	dering and	1011.5	192.168.100.15	Minor	Registration failed	2024-07-11	330		(Č) ()	,

• Real-time alarm notification and equipment failure monitoring


		44 1	ndex Busin	ess Analysis O	Device Lis	10										÷	Clo
Profile Management		Dev	rice Name :			Device	Model-			MAC:				iP:			
			vice Name			001100			~	MAC				iP			
	4	52.0	tus:			Firmwa	re :			DND Statu	a			Site:			
Device Management			gistered						~				~				i.
Device Management		Cre	ater:														
	4																
Task Management	2	-															
Task Management	<u> </u>	Q.54	arch 278es	44													
Dashboard	*	+ Ad	to Delate	±lmport.	PEaport	Commissed To	emplato 🔝	ync førs	Cancel Synt RP	O Config	g Sync RPS	Mere -					
			Device Name	Device Mode	MAC	IP	Status	Firmware	Subnet	Sync RPS	RPS Cfg Url	Bind Accourt	Site	Create Time	Creater	Operate	
		-	Circles Int	11/21/52	00:11:00	10.0.0.157	Decistered -	5.42.1.7.1.38	246 246 256 /			Yes		2024.06.11.0	HtekSupport	08	-
	-			00702	00.11.00.000.	10.0.0.107	Heyisteles *	0.942.1.7.1.301	200.200.200.0	NO		115		2024-00-11 0	niekouppun	68	140
	5		h	UCV50	00:1f====ii	172.17.3.35	Registered -	5.42.1.7.1.30	255.255.252.0	860		Yes		2024-04-15 0	HtekSupport	6	0
	÷.			UCV/2	00-11-0-0-0	192 168 100	Registered +	5.42.1.7.1.23	255 255 255 (Yes		2024-03-11 0	HtekSupport	88	-
System Management								0.18111111800						2021-00-11-0	(acaropport	6	-
aystem management	2	0	1 phaleis	UC505	00:11:00	172.16.10.11	Registered -	2.42.6.6.49	255.255.255.0	No		Yes		2024-02-28 0	HtekSupport	6	101
		0	/ The second	LIC503	00-11-0101	172 16 10 11	Registered +	2.42.6.6.64	285 285 285 0			Yes		2024-02-28.0	HtekSupport	18 M	-
		-								-							-
			7.1.578	UCV53	00:1f:00 11:0	172.16.100.7	Registered -	5.42.1.7.1.238	255.255.255.0	No		Yes		2024-02-01 0	HtekSupport	6	101
		0	1.00	UCV50	02-11-201-2	10 10 8 171	Registered .	5.42.1.7.1.6R	255 255 255 (-		Tes		2024-02-01 0	HtekSupport	2 A	-
		-										-					
			Eilles	UC924U	00:1failline	10.1.58.225	Registered -	2.42.6.5.45R5	255.255.255.0	No		Yes		2024-01-17 0	HtekSupport	6	101
		0	v	IPT10	00:11:00 - (bet	192.168.30.1	Registered -	5.42.1.6.32R1	255.255.255.0	No		Tes		2023-12-29 0	HtekSupport	2 A	0
												_				_	
		0	V-11- 05	VP921	9:00	192,168,30,1	Registered +	2.42.6.5.45RE	255 255 255 0	1000		785		2023-12-25.0	HtekSupport	3	100

• Easy configuration, plug and play, flexible management




Customized UDMS for Unify





		WWW BANDICAM Com		
C @ Altorenze https://10200.52/vdec		# Q		
< C == C == C == C ==	1 1 tota 1 HE (1 HE (2 Loss 1) HEEE (2 Los (2 HE) (2	3 dese comuzame 🖸 nate 🗇 na 🗍 Ha 🗇 Ha 🗍	RE Massile St. RP05 C Pagarning C SAER	C Search 🕐 Other Searcher
DNS Managemen X			koost	
Rore X	UNIFY			
and the second		vofile Account Network Function Keys Settin	ngs Directory Management	
	warning. The follow users are using the default	password, please change the password/(admin,user)	x	
	and a second sec			
	Status • Version 3		NOTE	
	Product Model	Desk Phone DP10	Version:	
	Fernware Version		Storen reached have and the	
		ROM-0.23.8.26 (2023-08-28.06.23.00) DSP-0.0 3(Patch 1.0.16M)	version of ferroran	
		and the second second second	Account Status:	
	Account Statu		different the sugnitured alongs of	
	Account 1	11@1.5080 : Register Failed; UDP	And and a second s	
			Network:	
	Network 1		division that dottait information of 10000 port and CAN port.	
	IP Mode (Pv&P	V6) IPv4	Contraction Depters	
	Device Type	Bridge	System Up Time:	
	MAC Address	00.1fc1.20.ba/21	Mentana Mar Aperang Sens attact	
	Current Time	09-09-2023 04:20:24		
	VLAN ID	20	Reboot:	
	IPv4 Setting WAN Port Type	DHCP	Respective years again advect	
	WAN IP Address			
	Subret Mask	255.255.0.0		
	Gateway	10.20.0.1		
	Primary DNS	192.166.1.7		
	Secondary DNS	192.168.0.230		
	Memory Free	39684 KB		
	System Up Tim	ne 0 day(s) 0 hour(s) 8 min(s) 34 sec(s)		
	Reboot	Reboot		



	AS Management System	2							English - steph
	H Index Ste Mana	gement Ø Profile Group	0 Profile, Profile G	Youp - Company A O	Account O				H C:
Profile Management	Name:		Authenticate ID	E.	SIP User ID			abel:	
Account Management *	Namo Profile:		Autherskate ID Account Status		ISIP User ID Assign Sta			abel levice Name:	
Accourte	Profile				-	0.5		levice Name	
C Device Management	MAC: MAC		Creater:						
🛚 Config Management 🕓	QBearth CReent								
📓 Task Management 🤟	+Add BDeam	Linpot Misport A	Download Template						
🖵 Dashboard 🧹 🤆	Name	Authenticate ID	SIP User ID	Label	Profile	Account Status	Assign Status	Greater	Operate
Device Diagnosis	ACC-3968	5063	2063	2063	Profile - Support	Office	Unallocated -	steption	881
A Narm Management	D ACC-2064	2004	2064	2064	Profile - Support	Offine	Unaflocated -	slepten	881
Ø System Management C	C ACC-2965	2065	2065	2065	Profile - Support	Office	Unallocated +	stephen	881
	ACC-2066	2006	2008	2008	Profile - Support	Office	Unationated +	stephen	281
	D ACC-2007	2007	2067	2007	Profile - Support	Offine	Unaflocated +	stephen	881
	ACC-2068	2068	2066	2068	Profile - Support	Offine	Unallocated -	stephen	281
	C ACC-2069	2009	2009	2009	Profile - Support	Offine	Unaflocated -	sleption	881
	D ACC-2052	2052	2052	2052	Profile - Support	Offine	Unaflocated -	stephen	881
	View 11 - 18 of 18			н •	Page 2 of 2 in	10 m			
					D.				

Technology Partners













China Mobile A biggest operator in the world O2 Czech, Czech Republic, Mitel, Hosted Platform



Singtel, Singapore, Broadsoft



KPN, Netherlands, Routlt (based on Broadsoft)

MTS (Russia's biggest Mobile Operator), Russia, Broadsoft

МТС



Malta Only Telecom Operator Go, Broadsoft

Mitel UNFY El-Itek

UNFY Harmonize your enterprise



Technical Report

Test of DP 10 and DP 12 OpenScape Business V2R6 (Non-Portfolio Process – Project Specific)

Version: 1.0 Data: 04/06/2019

Unify - Soluções em Tecnologia da Informação LTDA Curitiba Brasil



Success Cases with Mitel-Unify






University of Sao Paulo, Brazi

Coorperate model: DP12



Shanghai Pudong Development Bank, China

Coorperated Model: UC503P




Dr. António Agostinho Neto International Airport, Angola

Coorperated Model: UC503G

Why Htek





THANKS

(S) www.htek.com

Hanlong Techonlogy(Nanjing)Co.,Ltd. Tel +86-25-84658050 Fax +86-25-84658319